


Manuell reglering – värme

When $T > T_s$: The motor is OFF.

When $T < T_s$: The analogue output is according to the following diagram



T_s = Temperature set point: 5 – 35 °C