


Automatisk reglering – värme



T_s = Temperature set point: 5 – 35 °C

Proportional range = 2 °C